



PACKING LIST FOR FAR2127BB

Box 1 - Processor Unit WT: 29 Lbs DIM: 19"W x 21"L x 12"H

<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	RPU013H Processor Unit	1
2	000-808-981 Terminal Spanner Tool "20mm"	1
3	000-147-517 Terminal Spanner Tool "19mm"	1
4	000-538-118 Crimp Lug FV2-4	2
5	000-549-065 Fuse FGBO 10 for "AC" Unit	4
6	000-549-015 Fuse FGBO 20 for "DC" Unit	4
7	IME-351-90Z Installation Manual	1
8	OME-351-90Z Operator's Manual	1

Box 2 - Control Unit WT: 10 Lbs DIM: 11"W x 19"L x 8"H

<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	RCU014 Control Unit w/ Cable Assembly	1
2	100-306-251 Fixing Bracket	1
3	000-147-167 Grommet "G39"	1
4	000-803-043 "3M" Brand Bumper Cushion	3
5	000-881-447 Washer Head Screw M4 x 12	2
6	000-881-447 Washer Head Screw M4 x 12	4

Box 3 - Gearbox WT: 71 Lbs DIM: 16" W x 23"L x 24"H

<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	RSB096-079A Gearbox w/ RTR079 25KW T/R	1
2	300-130-010 Corrosion Proof Mat	1
3	300-130-020 Seal Washer	4
4	000-808-981 Terminal Spanner Tool	1
5	000-538-123 Crimp Lug FV5.5-4	1
6	000-863-112 Hex Nut M12	4
7	000-864-132 Flat Washer M12	4
8	000-864-263 Spring Washer M12	4
9	000-862-191 Hex Bolt M12 x 60	4
10	000-863-109 Hex Nut M6	1
11	000-864-129 Flat Washer M6	3
12	000-864-260 Spring Washer M6	1
13	000-862-180 Hex Bolt M6 x 25	1
14	000-566-000 Grounding Wire	1
15	000-631-716 Motor Brush	2

Box 4 - Cable WT: 58 Lbs DIM: 19"W x 21"L x 12"H

<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	000-149-193 30M Cable Assembly	1

For Internal Use Only	
Serial No. 4318 -	
Checked By:	
Tech	_____
Date	_____
RPU-013H	
<u>Yes</u>	<u>Remarks</u>
	sub 008-535-940
	"
	"
	008-535-910
	008-535-950

RCU-014	
<u>Yes</u>	<u>Remarks</u>
	sub 008-535-610
	"
	"
	"
	sub CP03-25604

RSB096-079A	
<u>Yes</u>	<u>Remarks</u>
	sub 008-535-550
	"
	"
	"
	"
	"
	"
	"
	"
	"
	"
	sub 008-435-860

000-149-193	
<u>Yes</u>	<u>Remarks</u>