

FURUNO

PACKING LIST FOR GS100

Box 1 - GS1001 Wt: 11 lbs. Dim: 32" x 14" x 11"

	<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	GS1001	Antenna Unit	1
2	100-340-192	Rubber Bushing	1
3	000-162-186-10	Cable Tie CV-150N	3
4	000-167-490-10	Hex Nut M10	8
5	000-167-416-10	Flat Washer M10	8
6	000-167-389-10	Spring Washer M10	8

Box 2 - GS1002 Wt: 10 lbs. Dim: 20" x 11" x 9"

	<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	GS1002	Display Unit	1
2	001-105-800-10	NMEA2K Cbl Assy 6m	1
3	001-265-430-00	Cable Assy 6m	1
4	000-154-054	NMEA Cbl Assy 5m	1
5	100-360-672-10	LCD Cleaning Cloth	1
6	000-162-608-10	Tapping Screw 5x20	4
7	000-172-164-10	Cable Tie CV-125N	1
8	OME-727-90Z	Operator's Manual	1
9	MDC-727-90Z	Environmental Data Sheet	1

Box 3 - GS1003 Wt: 3 lbs. Dim: 13" x 8" x 6"

	<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	GS1003	Junction Box	1
2	000-158-850-10	Tapping Screw 4x20	4
3	000-162-167-10	Cable Tie CV-100N	1
4	000-157-481-10	Fuse 3A 125V	1

For Internal Use Only	
Serial No. _____	
Checked By: _____	
Tech _____	
Date _____	
GS1001	
<u>Yes</u>	<u>Remarks</u>
	CP20-03501
	"
	"
	"
	"

GS1002	
<u>Yes</u>	<u>Remarks</u>
	CP20-03401
	"

GS1003	
<u>Yes</u>	<u>Remarks</u>
	CP20-03701
	"
	SP20-01501