

# FURUNO

## PACKING LIST FOR DRS6ANXT

For Internal Use Only	
Serial No. _____	
Checked By: _____	
Tech _____	
Date _____	

Box 1 - RSB137-119	Wt: 41 lbs. Dim: 20" x 18" x 16"
--------------------	----------------------------------

	<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	RSB137-119	Scanner Unit	1
2	000-192-660-10	Fuse ATV10A60V	1
3	000-193-631-10	Fuse ATV15A60V	1
4	100-403-040-10	Corrosion-proof rubber mat	4
5	000-167-491-10	Hex Nut M12	8
6	000-167-397-10	Spring Washer M12	4
7	000-167-417-10	Flat Washer M12	4
8	000-191-051-10	Hex Stud M12x70	4
9	IME-366-80Z	Installation Manual	1
10	C32-007-03Z	Mounting Template	1
11	MDC-366-80Z	Environmental Data Sheet	1

DRS137-119	
<u>Yes</u>	<u>Remarks</u>
	SP03-19101
	SP03-19101
	CP03-37101
	"
	"
	"
	"

Box 2 - 000-033-480-00	Wt: 9 lbs. Dim: 17" x 17" x 8"
------------------------	--------------------------------

	<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	000-033-452-00	Signal/Power Cable Assy 10M	1

000-033-453-00	
<u>Yes</u>	<u>Remarks</u>