

FURUNO

PACKING LIST FOR FAR1518

Box 1 - RPU024/1518 Wt: 23 lbs. Dim: 20" x 19" x 12"

<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>	
1	RPU024/1518	Processor Unit	1
2	RCU028	Control Unit	1
3	000-155-827	Fuse 15A 125V	2
4	001-132-960	DVI Cable Assy 5M	1
5	100-372-550-10	Blind Seal	1
6	000-162-841-10	Insulation Tube 50CM	8
7	000-162-608	Tapping Screw 5X20	4
8	000-158-850	Tapping Screw 4X20	4
9	OME-363-80Z	Operator's Manual	1
10	MLG-363-80Z	Operator's Guide Multi-Language	1
11	IME-363-80Z	Installation Manual	1
12	MDC-363-80Z	Environmental Data Sheet	1

Box 2 - RSB120-100 Wt: 71 lbs. Dim: 24"x 23"x 16"

<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>	
1	RSB120-100	Gearbox	1
2	300-130-020	Seal Washer	4
3	300-130-020-10	Corrosion Proof Mat	1
4	000-166-744-10	Crimp-on Lug FV5.5-4	1
5	000-167-491-10	Hex Nut M12	4
6	000-167-446-10	Flat Washer M12	4
7	000-167-397-10	Spring Washer M12	4
8	000-162-813-10	Hex Bolt M12x60	4
9	000-158-856	Hex Nut M6	1
10	000-158-855	Spring Washer M6	1
11	000-158-854	Flat Washer M6	3
12	000-162-871-10	Hex Bolt M6x25	1
13	000-566-000	Grounding Cable (340mm)	1
14	000-190-125-10	Carbon Brush	2

<i>For Internal Use Only</i>	
Serial No. _____	
Checked By: _____	
Tech _____	
Date _____	
RPU024/1518	
<u>Yes</u>	<u>Remarks</u>
	SP03-18001
	CP03-36501
	"
	"
	CP03-36601

RSB120-100	
<u>Yes</u>	<u>Remarks</u>
	CP03-33401
	"
	"
	"
	"
	"
	"
	"
	"
	"
	"
	"
	"
	"
	SP03-12501